

Specification QX Series™



Nm



rpm



kg



mm



mm



V



in



Communication

QXN Cordless Tools

QX Series™ Cordless Precision Screwdriver								
QXN2PT04PQ4	0.8–4	1,500	0.91	215.4	20.3–26.0	20V	1/4"	Via USB Cable
QXN2PT04PS4	0.8–4	1,500	0.91	208.3	20.3–26.0	20V	1/4"	Via USB Cable
QXN2PT04PS6	0.8–4	1,500	0.91	212.0	20.3–26.0	20V	3/8"	Via USB Cable
QXN2PT08PQ4	1.6–8	1,150	0.91	215.4	20.3–26.0	20V	1/4"	Via USB Cable
QXN2PT08PS4	1.6–8	1,150	0.91	208.3	20.3–26.0	20V	1/4"	Via USB Cable
QXN2PT08PS6	1.6–8	1,150	0.91	212.0	20.3–26.0	20V	3/8"	Via USB Cable
QXN2PT12PQ4	2.4–12	750	0.91	215.4	20.3–26.0	20V	1/4"	Via USB Cable
QXN2PT12PS4	2.4–12	750	0.91	208.3	20.3–26.0	20V	1/4"	Via USB Cable
QXN2PT12PS6	2.4–12	750	0.91	212.0	20.3–26.0	20V	3/8"	Via USB Cable
QXN2PT18PQ4	3.6–18	500	0.91	215.4	20.3–26.0	20V	1/4"	Via USB Cable
QXN2PT18PS6	3.6–18	500	0.91	212.0	20.3–26.0	20V	3/8"	Via USB Cable
QX Series™ Angle Wrench								
QXN2AT05PQ4	1.0–5	1,213	1.14	552	9.2	20V	1/4"	Via USB Cable
QXN2AT10PS6	2.0–10	936	1.18	525	12.5	20V	3/8"	Via USB Cable
QXN2AT15PS6	3.0–15	600	1.18	525	12.5	20V	3/8"	Via USB Cable
QXN2AT18PQ4	3.6–18	500	1.27	542	13	20V	1/4"	Via USB Cable
QXN2AT18PS6	3.6–18	500	1.27	542	13	20V	3/8"	Via USB Cable
QXN2AT27PS6	5.4–27	330	1.68	552	17	20V	3/8"	Via USB Cable
QX Series™ High Torque Angle Wrench								
QXN5AT20PS06	4.0–20	1,045	2.04	577.7	13.1	40V	3/8"	Via USB Cable
QXN5AT30PS06	6.0–30	775	2.18	581.8	17.2	40V	3/8"	Via USB Cable
QXN5AT30PS08	6.0–30	775	2.18	581.8	17.2	40V	1/2"	Via USB Cable
QXN5AT35PS06	7.0–35	640	2.18	581.8	17.2	40V	3/8"	Via USB Cable
QXN5AT35PS08	7.0–35	640	2.18	581.8	17.2	40V	1/2"	Via USB Cable
QXN5AT40PS08	8.0–40	545	2.27	586.1	21.6	40V	1/2"	Via USB Cable
QXN5AT80PS08	12.0–80	375	2.27	586.1	21.6	40V	1/2"	Via USB Cable

QXC Cordless Tools

QX Series™ Cordless Precision Screwdriver								
QXC2PT04PQ4	0.8–4	1,500	0.91	215.4	20.3–26.0	20V	1/4"	Via USB Cable
QXC2PT04PS4	0.8–4	1,500	0.91	208.3	20.3–26.0	20V	1/4"	Via USB Cable
QXC2PT04PS6	0.8–4	1,500	0.91	212.0	20.3–26.0	20V	3/8"	Via USB Cable
QXC2PT08PQ4	1.6–8	1,150	0.91	215.4	20.3–26.0	20V	1/4"	Via USB Cable
QXC2PT08PS4	1.6–8	1,150	0.91	208.3	20.3–26.0	20V	1/4"	Via USB Cable
QXC2PT08PS6	1.6–8	1,150	0.91	212.0	20.3–26.0	20V	3/8"	Via USB Cable
QXC2PT12PQ4	2.4–12	750	0.91	215.4	20.3–26.0	20V	1/4"	Via USB Cable
QXC2PT12PS4	2.4–12	750	0.91	208.3	20.3–26.0	20V	1/4"	Via USB Cable
QXC2PT12PS6	2.4–12	750	0.91	212.0	20.3–26.0	20V	3/8"	Via USB Cable
QXC2PT18PQ4	3.6–18	500	0.91	215.4	20.3–26.0	20V	1/4"	Via USB Cable
QXC2PT18PS6	3.6–18	500	0.91	212.0	20.3–26.0	20V	3/8"	Via USB Cable
QX Series™ Angle Wrench								
QXC2AT05PQ4	1.0–5	1,213	1.14	552	9.2	20V	1/4"	Via USB Cable
QXC2AT10PS6	2.0–10	936	1.18	525	12.5	20V	3/8"	Via USB Cable
QXC2AT15PS6	3.0–15	600	1.18	525	12.5	20V	3/8"	Via USB Cable
QXC2AT18PQ4	3.6–18	500	1.27	542	13	20V	1/4"	Via USB Cable
QXC2AT18PS6	3.6–18	500	1.27	542	13	20V	3/8"	Via USB Cable
QXC2AT27PS6	5.4–27	330	1.68	552	17	20V	3/8"	Via USB Cable
QX Series™ High Torque Angle Wrench								
QXC5AT20PS06	4.0–20	1,045	2.04	577.7	13.1	40V	3/8"	Via USB Cable
QXC5AT30PS06	6.0–30	775	2.18	581.8	17.2	40V	3/8"	Via USB Cable
QXC5AT30PS08	6.0–30	775	2.18	581.8	17.2	40V	1/2"	Via USB Cable
QXC5AT35PS06	7.0–35	640	2.18	581.8	17.2	40V	3/8"	Via USB Cable
QXC5AT35PS08	7.0–35	640	2.18	581.8	17.2	40V	1/2"	Via USB Cable
QXC5AT40PS08	8.0–40	545	2.27	586.1	21.6	40V	1/2"	Via USB Cable
QXC5AT80PS08	12.0–80	375	2.27	586.1	21.6	40V	1/2"	Via USB Cable